

# Carbon Dioxide Monitor Model 2156 3% CO,

#### Features:

- Complete self contained units
- Non Dispersive InfraRed (NDIR) technology No moving parts gas diffusion sampling
- ECONO-CAL™ gas calibration kit
- Industrially robust: 0-5 V and 4-20 mA outputs Dust-tight water resistant fiberglass enclosure
- Dual adj level detect set points and relays
- Fast warm-up
  - Humidity and moisture resistant

Rear view:

• Solid state throughout - linear outputs

Cost effective - High quality

- **Digital** readout with 0.56 inch **RED** LED display
- Built-in Alarm beeps (switch to disable)at low set point, on at high set point Dual SET Point indicators

# Model 2156 3% CO

#### **GREEN** Power ON Indicator

#### YELLOW Low Limit Exceeded Indicator

**RED** High Limit Exceeded Indicator



Cable grommet for signal wires and relay contact connections. AC power cable and plug. **Audio Alarm** beeps at low set point, on at high set point. Internal switch disables alarm

Fresh **air** is about **0.04**% (400 ppm)**CO**,

# 0.312 inch dia. inches 4 places inches

Clearance: 5 x 8.5 x 10.5 inches



## **Application:**

- Industrial Safety
- Mushroom Farms
- Wineries
- Breweries
- Food Processing
- with CO<sub>2</sub> Blasters

The *VALTRONICS* Model 2156 is a Non-Dispersive InfraRed (NDIR) carbon dioxide monitor for use as a **safety monitor**. It has linear 0 to 5 volt and 4-20 mA signal outputs that are proportional to the 0 to 3% CO<sub>2</sub>. See **Application Note A11** for OSHA defined safety levels for CO<sub>2</sub>. Dual adjustable level detects (Low Limit & High Limit) and relay contacts may be used for external control of fans, air vents, and external alarms.



# Carbon Dioxide Monitor Model 2156 3% CO,

#### **Description:**

The Model **2156** is a non dispersive **InfraRed** gas monitor designed as a fully functioning standalone unit for the continuous monitoring of carbon dioxide. The optical system is not effected by humidity. The diffusion gas cell is not effected by variations in relative humidity from 0 to 95%. It has a 0.56 inch high digital readout and two adjustable level detect circuits with associated front panel indicators (yellow and red) and SPDT relay contacts.

This low power, water resistant system makes this an ideal remote sensor to interface with any central control unit. It has **linear 0** to **5 volt** and **4** to **20 mA** current loop outputs. In either configuration, interfaced or stand-alone, this device is an excellent choice for any environment in which the level of carbon dioxide must be monitored or controlled.

## Specifications: 2156 3% CO,

<b>Specifications: 2200 6</b> /6 <b>30</b>
Method:
Gas: Carbon dioxide (CO <sub>2</sub> )
Range: 0-30,000 ppm (3%) CO <sub>2</sub>
Accuracy:
Repeatability: $\pm$ 1% of full scale (challenge with same gas sample and assure zero )
External Power Source: 115/220 VAC , 50/60 Hz (6 foot long power cord is standard)
Power Consumption:less than 8 watts @ 115 VAC
Adjustable Set Points:
SET POINT Relay Contact Rating: SPDT contacts: non-latching N.C., N.O. 3 amp max. at 250 VAC or 30 VDC
Display:
Output Signals:GREEN power on indicator
Voltage:
Current Loop:
Audio Alarms: Beeps once a second when Low SET Point is exceeded, continuous when High exceeded
Set Point Indicators:
Zero Drift at Constant Temperature: Less than 2% of full scale per month (random not cumulative)
Zero Noise atConstant Temperature: Less than 50 mV peak to peak measured during any 20 second period
measured on voltage output (equals less than $1\%$ of full scale)
Zero Drift due to Ambient Temperature: Less than 0.5% of full scale per degree Centigrade
Operating Temperature Range: 0 to 50°C (32° to 122°F) see <b>Application Note A12</b>
Storage Temperature Range:40 to +70°C (-40 to +158°F)
Operating Humidity Range: 0 to 95% RH (non-condensing) in gas cell, see Application Note A30
Weight: Less than 6 pounds (< 2.72 kilograms)
External Clearance Dimensions: . 5 inches high, 8.5 inches wide, 10.5 inches long
Mounting, four 0.312 inch dia holes Mounting centers 4.0 inch x 8.75 inch: see diagram
3463 Double Springs Road • Valley Springs, CA 95252 • (209) 754-0707 • FAX (209) 754-0104 e-mail: <b>bpynenb@goldrush.com</b> • Model 2156 3% • Page 2 of 4 • Revised: <b>April 20, 1999</b>



Terminal block TB1 has a linear 0 to 5 volt output signal on pin number 9 with respect to pin number 8 which is signal common. Pin number 7 has a linear 4 to 20 mA current loop signal referenced again to pin number 8. See the wiring diagram on page 4.

The table below shows both the linear 0 to 5 volt and the 4 to 20 mA current loop responses to 0 to 3.0% carbon dioxide diffusing through the gas cell. The wires from TB1 go through the strain relief cable grommet shown on page 4. The resulting wire bundle must be between 0.090 and 0.25 inch diameter to be properly stain reliefed.

**Gas Calibration** done near mid-scale will give the best accuracy over the entire range. **Certified 1.0** $\pm$ 0.02% CO<sub>2</sub> or **2.0** $\pm$ 0.04% CO<sub>2</sub> would be good for gas calibration every 6 months to a year.

		_	_		_	_
VA	, ,	ĸ	O	NI	$C_{i}$	S


3% Gas and 5 V full scale linear

V/12	KUNI	<del></del>		370 Gas	and 5 v	ruii scaie	imeai						
Gas	Output	±0.08%	CO2	4-20 mA	±0.08%	6 CO2	Gas	Output	±10% of	reading	4-20 mA	$\pm 10\%$ of	reading
in %	in volts	Max.	Min.	output	Max.	Min.	in %	in volts	Max.	Min.	output	Max.	Min.
0.00	0.000	0.130	-0.130	4.00	4.40	3.60							
0.05	0.083	0.213	-0.047	4.27	4.67	3.87	1.55	2.583	2.713	2.454	12.27	12.68	11.85
0.10	0.167	0.297	0.037	4.53	4.93	4.13	1.60	2.667	2.800	2.533	12.53	12.96	12.11
0.15	0.250	0.380	0.120	4.80	5.20	4.40	1.65	2.750	2.888	2.613	12.80	13.24	12.36
0.20	0.333	0.463	0.203	5.07	5.47	4.67	1.70	2.833	2.975	2.692	13.07	13.52	12.61
0.25	0.417	0.547	0.287	5.33	5.73	4.93	1.75	2.917	3.063	2.771	13.33	13.80	12.87
0.30	0.500	0.630	0.370	5.60	6.00	5.20	1.80	3.000	3.150	2.850	13.60	14.08	13.12
0.35	0.583	0.713	0.453	5.87	6.27	5.47	1.85	3.083	3.238	2.929	13.87	14.36	13.37
0.40	0.667	0.797	0.537	6.13	6.53	5.73	1.90	3.167	3.325	3.008	14.13	14.64	13.63
0.45	0.750	0.880	0.620	6.40	6.80	6.00	1.95		3.413	3.088	14.40	14.92	13.88
0.50	0.833	0.963	0.703	6.67	7.07	6.27	2.00	3.333	3.500	3.167	14.67	15.20	14.13
0.55	0.917	1.047	0.787	6.93	7.33	6.53	2.05	3.417	3.588	3.246	14.93	15.48	14.39
0.60	1.000	1.130	0.870	7.20	7.60	6.80	2.10	3.500	3.675	3.325	15.20	15.76	14.64
0.65	1.083	1.213	0.953	7.47	7.87	7.07	2.15	3.583	3.763	3.404	15.47	16.04	14.89
0.70	1.167	1.297	1.037	7.73	8.13	7.33	2.20	3.667	3.850	3.483	15.73	16.32	15.15
0.75	1.250	1.380	1.120	8.00	8.40	7.60	2.25	3.750	3.938		16.00	16.60	15.40
0.80	1.333	1.463	1.203	8.27	8.67	7.87	2.30		4.025	3.642	16.27	16.88	15.65
0.85	1.417	1.547	1.287	8.53	8.93	8.13	2.35		4.113	3.721		17.16	15.91
0.90	1.500	1.630	1.370	8.80	9.20	8.40	2.40		4.200	3.800		17.44	16.16
0.95	1.583	1.713	1.453	9.07	9.47	8.67	2.45	4.083	4.288		17.07	17.72	16.41
1.00	1.667	1.797	1.537	9.33	9.73	8.93	2.50	4.167	4.375		17.33	18.00	16.67
1.05	1.750	1.880	1.620	9.60	10.00	9.20	2.55	4.250	4.463		17.60	18.28	16.92
1.10	1.833	1.963	1.703	9.87	10.27	9.47	2.60		4.550		17.87	18.56	17.17
1.15	1.917	2.047	1.787	10.13	10.53	9.73	2.65	4.417	4.638		18.13	18.84	17.43
1.20	2.000	2.130	1.870	10.40	10.80	10.00	2.70	4.500	4.725	4.275		19.12	17.68
1.25	2.083	2.213	1.953	10.67	11.07	10.27	2.75	4.583	4.813	4.354	18.67	19.40	17.93
1.30	2.167	2.297	2.037	10.93	11.33	10.53	2.80	4.667	4.900	4.433	18.93	19.68	18.19
1.35	2.250	2.380	2.120		11.60	10.80	2.85	4.750	4.988		19.20	19.96	18.44
1.40	2.333	2.463	2.203		11.87	11.07	2.90	4.833	5.075	4.592	19.47	20.24	18.69
1.45	2.417	2.547	2.287	11.73	12.13	11.33	2.95	4.917	5.163	4.671	19.73	20.52	18.95
1.50	2.500	2.630	2.370	12.00	12.40	11.60	3.00	5.000	5.250	4.750	20.00	20.80	19.20

Accuracy =  $\pm 0.075\%$  CO2 from 0 to 1.5% CO2 and  $\pm 5\%$  of reading from 1.5 to 3% CO2

Chart Revised on 3-5-97







#10-32 screw may be replaced by a #10-32 hose barb for gas calibration

Caution: Note jumper configuration for either <u>115 VAC</u> (JP1 & JP2) or <u>230 VAC</u> (JP3 only) operation.

#### **Preventive Maintenance:**

Gas calibration should be done every six months. At least calibration with zero gas (nitrogen) every six months and both zero and span (certified 1% or 2% CO<sub>2</sub>) at least once a year. Span calibration using 1% CO<sub>2</sub> would give you better accuracy on the low end of the scale where most measurements will occur (see Application Note A11 for an example of typical Industrial Safety CO<sub>2</sub> measurements). A calibration log book where you record how much ZERO and SPAN had drifted before it was recalibrated will help you decide what the optimum duration between calibrations should be. See Application Note A35 for detailed calibration instructions. The flow rate should be set to about 0.3 Liters per minute.

